



THE UNITED REPUBLIC OF TANZANIA

MINISTRY OF WORKS

TANZANIA NATIONAL ROADS AGENCY



When you reply please specify:

Ref No.: CB.390/431/03

Date: 8th February, 2024

To: All Prospective Bidders

RE: REHABILITATION OF MTWARA – MINGOYO – MASASI ROAD (201 KM): LOT 1: MTWARA – MINGOYO SECTION (82.27 KM), MTWARA DUAL CARRIAGEWAY SECTION (3.82 KM) AND LOT 2: MINGOYO – MASASI SECTION (118.4 KM)

TENDER NO.: AE/001/2022-23/HQ/W/03 (TZ-TANROADS-378635-CW-RFB)

Please refer to the above heading.

2. Pursuant to Sub-Clauses 7.1 and 8.1 of the Instruction to Bidders, TANROADS issues the attached Clarification No. 2, and Addendum No. 2 respectively, to the Bidding Documents

Eng. I. G. Wambura
ACTING CHIEF EXECUTIVE



THE UNITED REPUBLIC OF TANZANIA

MINISTRY OF WORKS

TANZANIA NATIONAL ROADS AGENCY



**REHABILITATION OF MTWARA – MINGOYO – MASASI ROAD (201 KM): LOT 1:
MTWARA – MINGOYO SECTION (82.27 KM), MTWARA DUAL CARRIAGEWAY
SECTION (3.82 KM) AND LOT 2: MINGOYO – MASASI SECTION (118.4 KM)**

TENDER NO. AE/001/2022-23/HQ/W/03 (TZ-TANROADS-378635-CW-RFB)

Clarification No. 2

Date: 8th February 2024

With reference to the question prospective bidders and pursuant to Instructions to Bidders ITB 7.1, TANROADS is herewith providing clarifications as follows:

| S/N | Questions Asked | Responses |
|-----|--|--|
| | Lot 1 | |
| 1. | In preparation of the bidding documents, some discrepancies have been noticed and need to be clarified: | |
| | (i). The drawings of the Typical Cross section and structures are missing, please provide so the contractor could quote properly for relevant items | Refer to the List of Standard drawings provided |
| | (ii). In SS 1403, four (4) units of type 2 and type 3 house are required, but three (3) units of type 2 house and two (2) units of type 3 house are required in the BOQ, and in the drawings, it shows type 3 house are required in BOQ, and in the drawing, it shows type 3 house has eight (8) units, Please clarify | The houses shall be provide as per SS 1403 |
| | (iii). The construction period of the project is 24 (twenty four) months and defects notification period is 12 (twelve) months, but the quantity of series 14.01 (f), (g) and (h) are 42, 84, and 84 months | The quantities have been counted excluding mobilization period for each unit for pricing purposes |
| | (iv). In SS 1406, Site Cabin/office for Engineer is required, but the same is required in series 14.04. Please clarify | Series 14.04 is pay item for the provision and maintenance of site cabin |
| | (v). There is no design drawing for site cabin/office. Please provide | Drawings for site cabin should be provided by the bidder in line with the requirements of the Standard Specifications for Road Works 2000 Section 1400 subsection 1406-Site Cabin/Office |
| | (vi). In SS 1404, Contractor shall provide and erect for the duration of the contract site office for the exclusive use of the Engineer's staff. Is this requirement same as SS1406. If they are | They are different. |

| S/N | Questions Asked | Responses |
|---------|---|--|
| | different, there is no payment item given and design drawing in the bidding documents | Bidders are advised to adhere to the requirements of the bidding documents |
| (vii). | In SS 1405, Contractor shall provide a fully equipped Wash House. However, there is no payment item in the BOQ and design drawing in the Bidding documents. Please clarify | Bidders are referred to Bidding Documents Volume 1C - Work Requirements Part 2-Section VI 2A. Standard Specifications 1405 |
| (viii). | In SS 1407, 4-wheel drive station Wagon with maximum Engine capacity 4.2 litres diesel is required. However, in the BOQ, there is Engine capacity 3.0 litre only | The 3.0 litre engine is the minimum required engine capacity |
| (ix). | BOQ 21.05 requires "Banks and dykes" but no design drawing is found in the Bidding Document. Please clarify | Refer to the List of Standard drawings provided |
| (x). | SS 5600 to 5605 requires the contractor to construct weighbridge which will be paid in BOQ 56.03. However, there is no such payment item in the BOQ. Please clarify | Weighbridge is not provided in this Tender |
| (xi). | SS 5709 shows payment for soil Analysis of Top soil taken from site in BOQ 57.13. However, there is no such item in the BOQ. | Refer to the preamble to the BoQ Clause 5 |
| (xii). | The design drawing of item 2.3 (access and drainage for box culvert in BOQ 6000 is missing. Please provide | Refer to response for question No (ix) above |
| (xiii). | Item 4.2 (b): "Key Activities" of eligibility and Qualifications criteria requires the contractor has completed (ii) Construction in situ concrete works – 180,000m ³ per year of any of the contracts, which seems to high. Please consider to reduce the requirement | Bidders are advised to abide by the requirements of the bidding documents |

| | | |
|----|---|---|
| | Lot 2 | |
| 2. | In preparation of the bidding documents, some discrepancies have been noticed and need to be clarified: | |
| | (i). The drawings of the Typical Cross section and structures are missing , please provide so he contractor could quote properly for relevant items | Refer to the List of Standard drawings provided |
| | (ii). SS 1403 and BOQ 14.01 (d) all describe four blocks of 4 units of multiple accommodation units but the drawing show it has eight (8) units. Please, clarify | Bidders are advised to price as per SS 1403 and BoQ |
| | (iii). In SS 1406, site cabin office for Engineer is required, but the same is required in series 14.04 in BOQ. Please clarify. | Series 1404 is pay item for provision and maintenance of the site cabin |
| | (iv). There is no design drawing for site cabin / office, please provide | Bidders are referred to Bidding Documents Volume 1C - Work Requirements Part 2-Section VI 2A. Standard Specifications 1406 They are different. |
| | (v). In SS 1404, the contractor shall provide and erect for the duration of the contract a site office for the exclusive use of the Engineer's staff. Is this requirement same as SS 1406? If they are different, there is not payment item and design drawing for this in the BOQ. | Bidders are advised to adhere to the requirements of the bidding documents |
| | (vi). In SS 1405, Contractor shall provide a fully equipped Wash hose. However, there is no payment item in the BOQ and design drawing in the bidding documents | Bidders are referred to Bidding Documents Volume 1C - Work Requirements Part 2-Section VI 2A. Standard Specifications 1405 |
| | (vii). In SS 1407, 4-wheel drive station Wagon with maximum Engine capacity 4.2 litres diesel is required. However, in the description in BOQ is Engine capacity 3.0 litre only. Please clarify | The 3.0 litre engine is the minimum required engine capacity |

| | | |
|--|--|---|
| | viii). BOQ 21.05 requires "Banks and dykes" but no design drawing is found in the bidding document. Please clarify | Refer to the List of Standard drawings provided |
| | (ix). SS 5600 to 5605 requires Contractor to construct weighbridge which will be paid in BOQ 56.03. However, there is no such payment in BOQ. Please clarify | Weighbridge is not provided |
| | (x). SS 5709 shows the payment for soil analysis of top soil taken from site in BOQ 57.13. However, there is no such item in the BOQ, please clarify | Refer to the preamble to the BoQ Clause 5 |

THE UNITED REPUBLIC OF TANZANIA

MINISTRY OF WORKS



Good roads for national development

REHABILITATION OF MTWARA – MINGOYO – MASASI ROAD (201 KM): LOT 1: MTWARA – MINGOYO SECTION (82.27 KM), MTWARA DUAL CARRIAGEWAY SECTION (3.82 KM) AND LOT 2: MINGOYO – MASASI SECTION (118.4 KM)

TENDER NO. AE/001/2022-23/HQ/W/03 (TZ-TANROADS-378635-CW-RFB)

Addendum No. 2

Date: 8th February, 2024

Addendum No. 2 to the Bidding Documents is issued in accordance with Instructions to Bidders, Clause 8.1 to effect changes to the Bidding Documents and will become binding document, overriding the original provisions to the applicable extent indicated. All other items and conditions of the original Bidding Documents remain unchanged. The following provisions of the Bidding Documents are amended as follows:

Item 1

Replace:

Drawings Nos. TRD/MMRD/XS/01, TRD/MMRD/XS/02, and TRD/MMRD/XS/03 issued with the Bidding Documents (Referring to Asphalt Concrete Surfacing).

With:

The same Drawing Nos TRD/MMRD/XS/01, TRD/MMRD/XS/02, and TRD/MMRD/XS/03 but referring to Asphalt Concrete Superpave Surfacing. Refer Pdf file with Title "Volume 2 – Eng. Drawings – Typical cross section Drawings – Mtwara – MingoYO – Masasi".

Item 2

List of standard drawings were missing in the issued Bidding Documents. They are now issued as:

Folder with Title "List of Standard drawings" containing 9 pdf files. Refer Pdf file with Title "Vol 1A – Final Design Report" which contains bridge design information; and

Item 3

Bridges Drawings were missing in the issued Bidding Documents. They are now issued as:

Section 6 of 6: Bridge and Hydraulics Structures Design in VOLUME 1A: FINAL DETAILED ENGINEERING DESIGN REPORT of Volume 1; FINAL REPORT and APPENDICES – CONSULTANCY SERVICES FOR DETAILED ENGINEERING DESIGN, PRELIMINARY ENVIRONMENTAL & SOCIAL IMPACT ASSESSMENT, ECONOMIC EVALUATION AND PREPARATION OF TENDER DOCUMENTS FOR REHABILITATION OF MTWARA – MINGOYO – MASASI ROAD (200KM): CONTRACT NO. TRD/HQ/1018/2011/12.

All Prospective Bidders who purchased the Bidding Documents are requested to bring **New Flash Disc of not less than 1GB** to collect the soft copies of the drawings (mentioned from (i) to (iii) above) at:

Tanzania National Roads Agency (TANROADS) HQ,
2nd Floor, Room No. 44,
10 Shaaban Robert Road/Garden Avenue Junction,
P. O. Box 11364,
Dar es Salaam,
Tanzania.
Tel.: +255 22 292 66001/6,
Fax +255 22-2926011.
Email: tanroadshq@tanroads.go.tz or pmu@tanroads.go.tz.

Note: The drawings will also be issued through Prospective Bidders' contact email addresses provided in their applications for purchase of Bid Documents.